Suppression Repair PIO

Soberanes

CA-BEU-003422

10/6/2016

REPAIR

North Repair Group

North of North Repair Group

East Zone

South of North Repair Group

West Repair Group

West Zone

South Repair Group

DIV T

DIV S

DIV P

DIV O

DIV N

DIV UU

DIV SS

DIV PP

DIV II

DIV GG

DIV CC

DIV AA

DIV M

DIV L

DIV K

DIV I

SANTA LUCIA

VENTANA WILDERNESS

FORT HUNTER LIGGETT MILITARY RESERVATION

Repair Status

- Outside Forest Service Admin Boundary
- No Repair Needed
- To Be Repaired
- Partially Complete
- Requires Post Incident Repair
- Pending READ Approval
- Repair Complete

- Communication Site
- Drop Point
- Water Development & Draft Site
- Fence
- Fish Habitat Concern
- Gates
- Helispot or Incident Base
- Mobile Weather Unit
- Other
- Retardant / Mud Pit
- Road Barrier
- Road Repair
- Safety Zone
- Sling Site
- Spike Camp
- Staging Area

- Uncontrolled Fire Edge
- Completed Line
- Road as Completed Line
- Line Break Completed
- Completed Dozer Line
- Hand Line
- Proposed Dozer Line
- Planned Fire Line
- Planned Secondary Line
- Ridge/Geographic Feature
- Transmission Lines
- Wilderness
- Administrative Forest
- State Park Boundary
- USDA Forest Service
- Bureau of Land Management

Suppression Repair Map
(Open with Avenza)

Repair Plan
(Open with QR Reader)

Central Coast Incident Management Team

N

0 1 2 Miles