

Suppression Repair PIO

Soberanes

CA-BEU-003422

10/7/2016

REPAIR

Repair Status

- Outside Forest Service Admin Boundary
- No Repair Needed
- To Be Repaired
- Partially Complete
- Requires Post Incident Repair
- Pending READ Approval
- Repair Complete

- Communication Site
- Drop Point
- Water Development & Draft Site
- Fence
- Fish Habitat Concern
- Gates
- Helispot or Incident Base
- Mobile Weather Unit
- Other
- Retardant / Mud Pit
- Road Barrier
- Road Repair
- Safety Zone
- Sling Site
- Spike Camp
- Staging Area

- Uncontrolled Fire Edge
- Completed Line
- Road as Completed Line
- Line Break Completed
- Completed Dozer Line
- Hand Line
- Proposed Dozer Line
- Planned Fire Line
- Planned Secondary Line
- Ridge/Geographic Feature
- Transmission Lines
- Wilderness
- Administrative Forest
- State Park Boundary
- USDA Forest Service
- Bureau of Land Management

Central Coast Incident Management Team

N

0 1 2 Miles